

More simplicity for complex processes:
The integrated WAGNER control and operating system WICOS
enables highest efficiency in surface coating.



Reduce resources and unit costs with WICOS.



Easy, safe & fast operation

Control all coating processes using the 15.6" multi-touch display with intuitive keys, helpful visualizations and clear icons. The machine status is always visible at a glance.



Efficient & continuous coating

Activate unused potential with automatic functions such as gap, height and depth control. For very complex geometries, we offer an optimal solution with dynamic 3D coating.



Future-proof control system

Integrate WICOS into your production environment via interfaces to ERP, MES, other third-party systems as well as COATIFY. Benefit from investment protection through update and upgrade capability.

● Included ○ Alternative □ Optional

WICOS **WICOS**
Plus

| | | | |
|-----------------------------|--|---|---|
| Powder center | IPS (max. 36 guns) | | ○ |
| | PXS (max. 36 guns) | ○ | ○ |
| | PXM (max. 34 guns) | ○ | |
| | PXE (max. 22 guns) | ○ | |
| | Powder center interface | | ○ |
| | Basic powder center | | ○ |
| HMI | 15.6" (IPS: always external) | ● | ● |
| | External touchscreen (mirroring) 15.6" | □ | □ |
| Operation | Conveyor control comfort via interfaces | □ | □ |
| Gun control | Gap control | ● | ● |
| | Height control 32 segments (vertical only) | ● | ● |
| | Height control 32 segments (horizontal, fixed long stroke) | ● | ● |
| | Hook & hanger protection | ● | ● |
| | Multi-zone coating | | □ |
| | Robot interface coating on/off (WAGNER Slave) | □ | □ |
| Motion control | Height positioning | ● | ● |
| | Depth positioning | ● | ● |
| | Synchronous stroke | ● | ● |
| | Active Sinus Regulation (ASR) | ● | ● |
| | Depth control | ● | ● |
| | Z-axis depth control 3D | | □ |
| | Dynamic 3D coating | | □ |
| | Multimotion control (step chain function) | | □ |
| After filter control | ECO mode (after filter with FI necessary) | □ | □ |
| | Active level control powder hopper residual powder discharge | □ | □ |
| | Active level control powder hopper recovery (after filter/ICF) | □ | □ |
| Job | Recipe management (1,000 recipes/local) | ● | ● |
| | Recipe management plus (10,000 recipes/external server) | □ | □ |
| | Recipe selection external via interface | □ | □ |
| | Recipe selection code plate (light bar activation) | □ | □ |
| | Color change modes | ● | ● |
| | Color management (only for systems with IPS) | | □ |
| Support | Alarm management | ● | ● |
| | WAGNER Device Tool (update/upgrade/back-up) | ● | ● |
| | Remote maintenance | □ | □ |
| | Diagnosis | ● | ● |
| Settings | User administration | ● | ● |
| | Recipe import/export | ● | ● |
| | Machine parameters (upload/download/back-up) | ● | ● |
| | Station view | ● | ● |
| Connectivity | COATIFY ready | ● | ● |
| | Data Hub (via OPC UA) | □ | □ |